



SAFETY ADVISORY

Issued by Angus Pinkerton Chairman Flying and Safety Committee 23rd March 2026

All pilots flying the Flare Prop paramotor wing should read this notice and take action before flying again.

Flare Prop – Mandatory A-Line Replacement

Flare has issued an important line update for the Flare Prop. Following internal quality testing, the manufacturer has decided to reinforce the A-lines (12 lines in total) in order to improve durability and long-term reliability. The updated lines are stated to have no impact on performance. In addition, the rubber line connected to the control handles has been slightly modified to improve handling and user experience. This modification is not described as safety related.

Flare has advised that the A-lines must be replaced before the next flight.

UK pilots should contact:

The Loft Paragliding Service Centre

Mike Millwood
Meadowview, The Street
Iford, BN7 3ER
Tel: 01273 516332
Email: info@theloftworkshop.co.uk

Pilots are asked to send their wing to the above service centre to have the update carried out. Flare has advised that shipping costs will be reimbursed. Pilots should email a copy of their shipping receipt to support@skywalk.org in order to receive reimbursement.